URS Greiner Woodward C	Alyde	
Job	Project No	Page of Sheet of
Description	Computed by	Date
· - · · · · · · · · · · · · · · · · · ·	Checked by	Date
Steve Bryant	TeehLaw/nc.	913-236-0006
Sandy Olinger	Amcom	256 313-1718
Heather Black	Titan	256-313-1710
Bob Skach	URS	913-391-1158
MIKE MASON	URS	913-344-1034
Matt Phoenix	URS	913-344-1085
I'm Harris	MONE	573 526-2736
Brud Eaton	USACE	716 983-3761
Jerry Preston	HODA BRAC-YERSON	9 404-464-63,75
Tom Lorenz	USEPA	913-551-7292
		164910021392 CUBD CUKX

40092734

SUPERFUND RECORDS

DRAFT

### **CONTINGENCY SAMPLING PLAN**

# SITE SPECIFIC ENVIRONMENTAL BASELINE SURVEY - ST. LOUIS ARMY AMMUNITION PLANT

The basis for this sampling plan is as follows:

- Soil borings to characterize sewer breaches will be installed within approximately 25 ft of each breach location where contaminants were detected in the sewer sediment or water samples immediately upstream of the breach. The relatively high hydraulic conductivity of the granular bedding material around the sewer lines, compared to the surrounding clays, would tend to transport contaminants away from the breach making closer sample intervals unnecessary.
- Beryllium detections above the screening level were observed in several locations across the site, typically in
  native clays deeper than 10 ft. below ground surface (bgs). Anecdotal evidence suggests that beryllium may be
  a naturally occurring constituent of the clay and not a site-related contaminant, therefore contingency samples
  are not recommended to address this contaminant. Also there is no exposure route in deep soils, making
  additional data unnecessary for the SSEBS or Risk Assessment.
- Copper was detected in one sample above the screening level at 0-0.5 ft. bgs in the parking area west of Building loutside the former billet storage yard. Since process knowledge does not indicate that metals were stored outside the yard, and the other samples from this boring and surrounding borings were well below the screening levels, further sampling is not recommended.
- Based on the investigation results and the Field Sampling Plan, the following additional contingency samples are recommended:

#### Sewers



- 10 Geoprobe borings (average 25-ft. depth)
  - 30 Samples for VOC, SVOC, PCB, Metals and TPH-DRO analysis
- <u>5 Sediment samples to determine presence of Dioxin in sewer system</u> (all locations previously sampled and in close proximity to Building 2)
  - 5 Samples for PCB and Dioxin analysis

#### Railroads

- 4 Geoprobe borings (1-ft. depth) to identify extent of 1,1-DCE at RA-RRSB-10
  - 4 Samples for VOC analysis

### Roadways

- 3 Geoprobe borings (1-ft. depth) to identify extent of antimony at RA-RDSB-16E
  - 3 Samples for Metals analysis
- 2 Geoprobe borings (10-ft. depth) to identify extent of 1,1-DCE at RA-RDSB-01E
  - 2 Samples for VOC analysis

### **Building 1**

- 3 Geoprobe borings (1-ft. depth) to identify extent of PCB at 01-SB10 Shallow
  - 3 Samples for PCB analysis

### **Building 2**

- 10 Geoprobe borings (10-ft. depth) to identify extent of PCB/Dioxin around building
  - 30 Samples for PCB and Dioxin analysis

### Building 4

2 Hand Auger borings (3-ft. depth) to investigate PCBs below concrete samples 04CS-02 and 04CS-03

4 Samples for PCB analysis

### **Building 6**

1 Hand Auger boring (5-ft. depth) to determine depth of Mercury and Pesticides at RA-06SB-04

• 1 Sample for Metals and Pesticide analysis

### **Building 7**

• 1 boring co-located with sewer boring (1-ft. depth) to identify extent of PCB at RA-07SB-02

• 1 Sample for PCB analysis

### Building 8

• 1 Geoprobe boring (1-ft. depth) to identify extent of 1,1-DCE at RA-08SB-05

• 1 Sample for VOC analysis

• 2 Geoprobe borings (12-ft. depth) to identify extent of TPH at 08SB-07

• 2 Samples for TPH-DRO analysis

### **Building 10**

 4 Geoprobe borings (20-ft. depth) to identify extent of TPH around former underground storage tanks (originally detected in SRSB-18 and SRSB-19)

• 4 Geoprobe borings (12-ft. depth) to identify extent of TPH at SRSB-16

8 Samples for TPH-DRO analysis

### No Additional Sampling

• Building 3.

• Building 5

Northeast Parking Area

• Groundwater

#### Totals

43 Geoprobe borings

3 Hand Auger borings

#### Analyses

35 Dioxin

34 Metals


1 Pesticide

73 PCB

30 SVOC

40 TPH-DRO

37 VOC



### **CONTINGENCY SAMPLING PLAN**

# SITE SPECIFIC ENVIRONMENTAL BASELINE SURVEY - ST. LOUIS ARMY AMMUNITION PLANT

The basis for this sampling plan is as follows:

- Soil borings to characterize sewer breaches will be installed within approximately 25 ft of each breach location
  where contaminants were detected in the sewer sediment or water samples immediately upstream of the breach.
  The relatively high hydraulic conductivity of the granular bedding material around the sewer lines, compared to
  the surrounding clays, would tend to transport contaminants away from the breach making closer sample
  intervals unnecessary.
- Beryllium detections above the screening level were observed in several locations across the site, typically in native clays deeper than 10 ft. below ground surface (bgs). Anecdotal evidence suggests that beryllium may be a naturally occurring constituent of the clay and not a site-related contaminant, therefore contingency samples are not recommended to address this contaminant. Also there is no exposure route in deep soils, making additional data unnecessary for the SSEBS or Risk Assessment.
- Copper was detected in one sample above the screening level at 0-0.5 ft. bgs in the parking area west of Building loutside the former billet storage yard. Since process knowledge does not indicate that metals were stored outside the yard, and the other samples from this boring and surrounding borings were well below the screening levels, further sampling is not recommended.
- Based on the investigation results and the Field Sampling Plan, the following additional contingency samples are recommended:

#### Sewers

- 10 Geoprobe borings (average 25-ft. depth)
  - 30 Samples for VOC, SVOC, PCB, Metals and TPH-DRO analysis
- 5 Sediment samples to determine presence of Dioxin in sewer system (all locations previously sampled and in close proximity to Building 2)
  - 5 Samples for PCB and Dioxin analysis

#### Railroads

- 4 Geoprobe borings (1-ft. depth) to identify extent of 1,1-DCE at RA-RRSB-10
  - 4 Samples for VOC analysis

### Roadways .

- 3 Geoprobe borings (1-ft. depth) to identify extent of antimony at RA-RDSB-16E
  - 3 Samples for Metals analysis
- 2 Geoprobe borings (10-ft. depth) to identify extent of 1,1-DCE at RA-RDSB-01E
  - 2 Samples for VOC analysis

#### Building 1

- 3 Geoprobe borings (1-ft. depth) to identify extent of PCB at 01-SB10 Shallow
  - 3 Samples for PCB analysis

### **Building 2**

- 10 Geoprobe borings (10-ft. depth) to identify extent of PCB/Dioxin around building
  - 30 Samples for PCB and Dioxin analysis

### **Building 4**

2 Hand Auger borings (3-ft. depth) to investigate PCBs below concrete samples 04CS-02 and 04CS-03

4 Samples for PCB analysis

### **Building 6**

• 1 Hand Auger boring (5-ft. depth) to determine depth of Mercury and Pesticides at RA-06SB-04

• 1 Sample for Metals and Pesticide analysis

## Building 7

• 1 boring co-located with sewer boring (1-ft. depth) to identify extent of PCB at RA-07SB-02

1 Sample for PCB analysis

### **Building 8**

• 1 Geoprobe boring (1-ft. depth) to identify extent of 1,1-DCE at RA-08SB-05

• 1 Sample for VOC analysis

• 2 Geoprobe borings (12-ft. depth) to identify extent of TPH at 08SB-07

• 2 Samples for TPH-DRO analysis

### **Building 10**

• 4 Geoprobe borings (20-ft. depth) to identify extent of TPH around former underground storage tanks (originally detected in SRSB-18 and SRSB-19)

• 4 Geoprobe borings (12-ft. depth) to identify extent of TPH at SRSB-16

• 8 Samples for TPH-DRO analysis

# No Additional Sampling

• Building 3

• Building 5

Northeast Parking Area

• Groundwater

#### Totals

43 Geoprobe borings

3 Hand Auger borings

#### Analyses

35 Dioxin

34 Metals

1 Pesticide

73 PCB

30 SVOC

40 TPH-DRO

37 VOC

### Agenda - January 15, 2003

- 0800 0830 Introductions / Begin Meeting
- 0830 1000 Preliminary Review of SSEBS Findings
- 1000 1015 Break
- 1015 1200 Introduce and Discuss Proposed Contingency Sampling Plan
- 1200 1300 Lunch
- 1300 1600 Discuss and Finalize Contingency Sampling
- 1600 1700 Develop Schedule for Contingency Sampling and Final Report Timetable

# ST. LOUIS ARMY AMMUNITION PLANT

# SITE-SPECIFIC ENVIRONMENTAL BASELINE SURVEY

Preliminary Review of SSEBS Findings

#### Outline

- · Site History
- Review of Environmental Baseline Survey (EBS) Report (December, 2000) and Development of Site-Specific EBS (SSEBS) Work Plan
- SSEBS Field Investigation
- · Results of SSEBS Field Investigation
- Baseline Human Health Risk Assessment (HHRA)

### Site History

- 1941: Begin St. Louis Ordnance Plant (SLOP) small arms production
- 1944: Conversion to 105 mm Howitzer shell production, designated as St. Louis Army Ammunition Plant (SLAAP)
- 1984: Renovated office space
- 1989: Industrial equipment removed
- 1998: Site vacant
- 2002: Demolition of Building 3

Review of Environmental
Baseline Survey (EBS) Report
(December, 2000) and
Development of Site-Specific
EBS (SSEBS) Work Plan

# Sampling Activities

- Installation/sampling of 9 monitoring wells
- Asbestos Containing Material (ACM) survey
- 34 soil borings
- 49 wipe samples
- 21 sediment/surface soil samples
- 4 wastewater/sump samples
- 24 concrete samples



# Areas Requiring Further Investigation

- · Site Wide
  - Sewer System
  - Underground Storage Tank (UST) areas
  - Transformer areas
  - Metal storage areas
  - Sumps
  - Groundwater

# Areas Requiring Further Investigation (cont.)

- . Building 1
  - Sumps (PCBs, Metals)
  - PCB oil stain
  - Metals in storage yard soils
  - Soils near breaking machines (PCBs, Metals)
  - Soils under building (TPH, PCBs, VOCs)

# Areas Requiring Further Investigation (cont.)

- Building 2
  - PCBs near former hydraulic fluid storage areas
  - Soils beneath building (TPH, SVOCs, PCBs, VOCs)
  - Sediment in manholes (VOCs)
  - Dioxin sampling at locations with PCB detections in high-heat areas

# Areas Requiring Further Investigation (cont.)

- · Building 4
  - = PCB oil stain
  - Sumps and compressor pits (PCBs)
- Building 5
  - Elevator (PCBs)
  - Storage area south of building (TPH)

# Areas Requiring Further Investigation (cont.)

- · Building 6
  - Lab and Darkroom (Metals)
  - Storage area south of building (TPH)
  - PCBs on basement surfaces
- · Building 7
  - ~ Oil stain (TPH)
  - Cooling Tower Blowdown Sediments (Cr+6)

# Areas Requiring Further Investigation (cont.)

- Building 8
  - SVOCs in soil
  - Pipe trench leading to Building 2 (TPH)
- · Building 9
  - Explosives in soil
- Building 10
  - UST closure not completed



# Site-Specific EBS (SSEBS) Work Plan

- Address areas identified as requiring additional investigation
- Collect unbiased data for a Baseline Human Health Risk Assessment (HHRA)
- · Phased approach to sample collection
  - Initial round of primary samples
  - Subsequent round of contingency samples to further define extent of contamination

# Site-Specific EBS (SSEBS) Work Plan (cont.)

- Establish Screening Levels (SLs) for Chemicals of Concern at the Site
  - Selection of SLs that ensures data that supports assessment of risk and allows flexibility in the decision making process
    - EPA Region IX Residential Preliminary Remediation Goals (PRGs)
    - Cleanup Levels for Missouri (CALM) Scenario A (Residential)
    - · Background levels determined for Metals and PAHs

### SSEBS Field Investigation

- Field work conducted from August 12 -September 20, 2002
- Most primary samples collected as planned except the following notable exceptions
  - Sewer system-
    - Sediment and Wastewater not found at all projected sampling locations - reduced number of samples
    - Sewers located very deep in areas, bedrock encountered prior to third sample depth

### SSEBS Field Investigation (cont.)

- · (Exceptions continued)
  - Building 1
    - Only one sump observed in SW corner, sample 01SB-09 eliminated
    - Obstruction encountered after collecting shallow and middle samples, offset to collect deep sample
  - Building 2
    - Concrete and Product samples not in Work Plan added for PCB analysis

# SSEBS Field Investigation (cont.)

- · (Exceptions continued)
  - Building 6
    - Wall in basement prevented access to sample locations RA-06SB-08 and RA-06SB-16, samples were not collected
  - Building 7
    - No Sediments observed beneath Cooling Tower, sample not collected
    - Piping and concrete between Cooling Tower and Pump House obstructed sampling equipment, deeper samples at RA-07SB-10 not collected

### SSEBS Field Investigation (cont.)

- (Exceptions continued)
  - Groundwater
    - Chloride and Fluoride analyses added to three of the new wells located near Fire Hydrant (also sampled for these new parameters)
    - Additional soil boring (08SB-MW02) sampled near monitoring well 08MW-02 due to odor encountered during installation of well

# Results of SSEBS Field Investigation

- Regional Background
- Building 8
- · Building 1
- . Building 10
- Building 2
- Northeast Parking Area
- Building 4
- · Railroads
- Building 5
- Roadways
- · Building 6
- · Sewer System
- · Building 7

- Groundwater

# Regional Background - Metals

Ţ	Minimum	Maximum	95% Upper
Parameter	Detection	Detection	Tolerance Limit
Antinuny -	nd	nd	Cal
Arsenic	3.4	18	21.4
Barium	154	376	679
Beryllium	0.57	1.4	1.6
Cadmium	1.9	6.3	7.1
Chronium	14	43	48.3
Соррег	17	348	404
Lead	34	876	1038
Mercury	0.025	0.35	0.44
Nickel	13	41)	45.7
Selenium	3.3	10	16.5
Silver	nd	nd	Da
Thallouni	0.17	0.44	0.53
Zinc	60	902	1068

Note: All results in mg/kg ns - not applicable nd - not detected

# Regional Background - PAHs

Parameter	Minlmum Detection	Musimum Detection	95% Upper Tolerance Limit
Acenaphthene	0.001	0.94	1.1
Acenaphthylene	0.001	0.165	0.31
Anthracene	0.004	2.4	2.8
Benzo(a)anthracene	_ 0,003	6.2	7.2
Benzo(s)pyrene	0,003	3.5	4.1
Benzo(b)fluoranthene	0.006	4,2	4.9
Benzo(g.h.i)perylene	0.023	2.1	2.5
Benzo(k)fluoranthene	0.002	2.1	2.5
Chrysene	0.005	6	7.0
Dibenz(a,h)anthracene	0.013	1.3	1.5
Fluoranthene	0.008	13	15.2
Fluorene	0.001	ı	1.2
Indeno(1,2,3-cd)pyrene	0.022	1.7	20
Naphthalene	0,002	0.165	0.37
Phenanthrene	0,003	13	15.2
Рутепо	0.008	11	12.8

# Building 1





# Building 1 Summary Table

• .	-	# of Samples with Detections above Screening Level					
Sample Type	# of _Samples Cullected	Metals	PAHs	PCBs	ТРН	VOCs	
Concrete	2	na	ŋ ä	1	ha	9.4	
Soil - Equipment Sumps	6		na.	0	0	4	
Soil - Billet Entry Points	. 9	0	84	ns	n a	0.4	
Soil - Billet Entry Points	3	- 42	0	0	0	0	
Soil - SW Sump	3	72	6.0	0	n.	na	
Soil - Process Sumps	9	0	0.4	1	0	na	
Soil - Billet Storage Yards	18	0	na.	na		0.0	
Soil - Risk Assessment	30	1	0	0	8.2	0	


# Building 1 Results

- Concrete
  - Samples collected at 0-1" and 2-3" depths from one
  - PCB-1254 detected at concentration of 0.43J mg/kg in 0-1" sample (Soil Screening Level (SL) = 0.22 mg/kg)
- - SE Process Sump sample 01SB-10(0-0.5) had detection of PCB-1254 at a concentration of 0.35 mg/kg (SL = 0.22 mg/kg)
  - Risk Assessment sample RA-01SB-03(0-0.5) had detection of Copper at 1260 mg/kg (SL = 1100 mg/kg)

The fire

# Building 2





# Building 2





# Building 2 Summary Table

	T	# of Samples with Detections abo Screening Level							
Sample Type	# of Samples Collected	Asheuns	Dioxin	Metals	PAHs	ž.	Æ	VOC	
Asbestos	20	0	па	na	n a	n.a	n.a	na	
Concrete	10,	na.	na.	na	n.	9	D.a	пц	
Product	2	п=	n.a	ha	04	1	B4	na	
Surface Wipe	i	Пě	D-B	na	na	1 *	n.	n s	
Soil – Equipment Areas	12	na	7	R.	U.	1	3	па	
Soil - Central Trench	15	na.	5	ħ.a	na	0	n=	па	
Soil – Test Pits	20	па	11	o	n2	3	4	ø	
Soil - Risk Assessment	36	na	13	0	0	1	na	ı	

# **Building 2 Results**

- Refractory Bricks
  - 2 types of refractory bricks were sampled
  - 10 samples of each
  - All samples were determined to be nonasbestos containing



# Building 2 Results (cont.)

- Concrete
  - All samples collected from 0-1" depth only
  - PCB-1248 detected in 9 samples at concentrations ranging from 0.411 to 9.6 mg/kg (Soil SL = 0.22 mg/kg)
  - PCB-1260 detected in 3 samples at concentrations ranging from 0.09J to 0.6 mg/kg (Soil SL = 0.22 mg/kg)




# Building 2 Results (cont.)

- Product
  - PCB-1248 detected at concentration of 10 mg/kg (Soil SL = 0.22 mg/kg) in 02PD-01 in SE corner of building
  - No PCBs detected in 02PD-02 from West Mezzanine







# Building 2 Results (cont.)

- · Surface Wipes
  - Sample was collected from oil-coated wires in a trench
  - PCB-1248 was detected (No Screening Level)




## Building 2 Results (cont.)

- · Soils
  - Dioxins
    - 36 Detections above Screening Level (TEQ SL = 2,3,7,8-TCDD EPA Region IX PRG = 3.9 pg/g)
      - 0 1 feet: 8 Detections above TEQ SL
      - 2 5 feet; 8 Detections above TEQ SL
      - 6 10 feet: 14 Detections above TEQ SL
      - 11 15 feet: 4 Detections above TEQ SL
      - >15 fect; 2 Detections above TEQ SL
    - Min = 3.917 pg/g; Mean = 52.60 pg/g; Max = 313.8 pg/g

# Building 2 Results (cont.)

- · Soils (cont.)
  - PCBs
    - 5 Detections of PCB-1248 above Screening Level (SL = 0.22 mg/kg)
    - Min = 1 mg/kg: Mean = 5 mg/kg; Max = 14 mg/kg
  - TPF
  - 7 Detections of TPH above Screening Level (SL = 200 mg/kg)
  - Min = 250 mg/kg; Mean = 1,675 mg/kg; Max = 3,603 mg/kg
  - VOC
    - 1,1-Dichloroethene detected at concentration of 0.11 mg/kg (SL = 0.054 mg/kg) at boring location RA-02SB-12 at a depth of 9 to 10 feet



# **Building 4 Summary Table**


	U			·						
					vith C ening					
Sample Type	# of Samples Collected	Metals	PAHs	PCBs	Pesticules	HE.	vočs			
Concrete	4	na	na	2	na	na	na			
Surface Wipe	4	na	na	0	na	na	na			
Soil - PCB Stain	3	nμ	na	0	ną	nu	na			
Soil - Compressor Pits -	6	na	na	0	na	0	na			
Soil - Risk Assessment	28	1	0	0	0	na	0			

# **Building 4 Results**

- Concrete
  - Samples collected at 0-1" and 2-3" depths from one location (04CS-01) and only 0-1" at two other locations
  - PCB-1248 detected at concentrations of 0.97 and 1.2 mg/kg in surface samples at 04CS-02 and 04CS-03 (Soil SL ≈ 0.22 mg/kg)
- \* Surface Wipes
  - No detections above the Screening Levels for PCBs

## Building 4 Results (cont.)

- Soils
  - No detections above Screening Levels for PAHs, PCBs, Pesticides, TPH or VOCs
  - One detection of Metals above Screening Level, Beryllium at RA-04SB-02
    - . Depth was 2 to 3'
    - · Concentration was 1.9 mg/kg
    - Screening Level = 1.6 mg/kg



# Building 5 Summary Table

		# of Samples with Detections above Screening Level						
Sample Type	# of Samples Collected	Exphosives	Metals	PAHs	Ę	Pesticides	H.H.	VOC5
Mastic	3	na	na	na	3*	כח	na	па
Surface Wipe	1	na	na	na	υ	בת	na	na.
Soil - Oil Storage Pad	3	u7	na	0	na	na	0	na
Soil - Risk Assessment	32	0	ı	1	0	1	na	0

## Building 5 Results

- Mastic
  - All 3 samples had detections for PCBs
  - PCB-1248: 0.41 1.5 mg/kg
  - PCB-1254: 0.22 3.1 mg/kg
- · Surface Wipe
  - No detections above the Screening Limit for PCBs

# Building 5 Results (cont.)

- Soil Borings
  - Oil Storage Pad no detections above the Screening Level for PAHs or TPH
  - Risk Assessment Locations
    - Only detections above Screening Level were at location RA-05SB-05, shallow depth of 0-6 inches
    - Metals
      - Lead detected at concentration of 1790 mg/kg (SL = 1039)


# Building 5 Results (cont.)

- · Soil Borings
  - -- Risk Assessment Locations (cont.)
    - PAHs detected above Screening Level
      - Benzo(a)anthracene · 25 mg/kg (SL = 7.2 mg/kg)
      - Benzo(a)pyrene 19 mg/kg (SL = 4.1 mg/kg)
      - Benzo(b)fluoranthene 16 mg/kg (SL = 4.9 mg/kg)
      - Benzo(g,h,i)perylene 14 mg/kg (SL = 2.5 mg/kg) - Benzo(k)(luoranthene - 19 mg/kg (SL = 6.2 mg/kg)
      - Benzo(k)/ndofantariele 19 mg/kg (SL = 0.2 mg/kg)
         Dibenz(a,h)anthracene 7.1 mg/kg (SL = 1.5 mg/kg)
      - indeno(1,2,3-ed)pyrene 11 mg/kg (SL = 2.0 mg/kg)
      - Phenanthrene 33 mg/kg (SL = 15.2 mg/kg)



# Building 5 Results (cont.)

- · Soil Borings
  - Risk Assessment Locations (cont.)
    - · Pesticides detected above Screening Level
      - 4,4'-DDE at concentration of 65 mg/kg (SL = 1.7 mg/kg)
      - 4,4'-DDT at concentration of 1,100 mg/kg (SL = 1.7)




# Building 6 Summary Table

		# of Samples with Detections above Screening Level							
Sample Type	# of Samples Collected	Explosives	Metals	PAHs	PCBs	Pesticides	SVOCs	HAL	vocs
Mastic	3	na	בה	na	3*	na	na	na	па
Sediment	1.,	uz	1	na	na	na	ø	na	n
Surface Wipe	1	пэ	0	na	na	na	0	na	0
Surface Wipe	4	na.	na	na	0	na	na	na	na
Soil - Oil Storage Pad	.3.	na	na	0	na	na	па	0	na
Soil Risk Assessment	28	0	5	C	0	2	na	na	Đ

# Building 6 Results

- Mastic
- - All 3 samples had detections for PCBs
- PCB-1248: 1.2 to 4.9 mg/kg
- PCB-1254: 0.73 to 10 mg/kg



# Building 6 Results

- · Sediment
  - Taken in Old HVAC System Duct
  - Metals detected above Screening Levels
    - Arsenic at concentration of 23 mg/kg (Soit SL = 21.4 mg/kg)
    - Chromium at concentration of 222 mg/kg (Soil SL = 210 mg/kg)
    - Lead at concentration of 2610 mg/kg (Soil SL = 1038 mg/kg)
    - . Mercury at concentration of 3.6 mg/kg (Soil St. = 0.6 mg/kg)



# Building 6 Results (cont.)

- · Surface Wipes
  - All detections below Screening Levels
- · Soil:
  - Oil Storage Pad no detections above the Screening Levels for PAHs or TPH
- · Risk Assessment Borings
  - 4,4' DDT detected above Screening Level (1.7 mg/kg)
  - at RA-06SB-04
    - 4 mg/kg at depth of 0 to 1/2 foot
    - 21 mg/kg at depth of 2 to 3 feet

# Building 6 Results (cont.)

- Risk Assessment Borings (cont.)
  - Beryllium and Mercury detected above Screening Levels (1.6 and 0.6 mg/kg) in the following borings
    - RA-06SB-02(0-0.5); Mercury at concentration of 1.5 mg/kg
    - RA-06SB-03(0-0.5); Beryllium at concentration of 1.6 mg/kg
    - RA-06SB-04(0-0.5); Mercury at concentration of 0.85 mg/kg
    - · RA-06SB-04(02-03): Moreury at concentration of 0.92 mg/kg
    - RA-06SB-05(0-0.5); Mercury at concentration of 0.94 mg/kg

# Building 7






# Building 7 Summary Table

	-				Detec	
Sample Type	# of Samples Collected	Metals	PAHs	PCBs	HH _	VOCs
Concrete	2	na	คอ	0•	1*	na
Soil - Oil Stain	: 3	na	na	ną	0	na
Soil - Risk Assessment	44	0	0	1	na	0

. One sample analyzed for each set of compound

# Building 7 Results

- Concrete
  - Samples collected at 0-1" (TPH analysis) and 2-3"
     (PCB analysis) depths from one location
  - TPH-DRO detected in surface sample only at a concentration of 2000 mg/kg (Soil SL = 200 mg/kg)
- Soils
- \_\_ Samples beneath oil stain in building were below Screening Level (200 mg/kg) for TPH
- Only detection in Risk Assessment samples was 0.34 mg/kg PCB-1254 at RA-07SB-02(0-0.5)



# Building 8 Summary Table

	•		•				
~		# of Samples with Detection above Screening Level					
Sample Type	# of Samples Collected	Metals	PAHs	PCBs	ТРН	vôcs	
Sediment	2	na	na	na	0	Uп	
Soil - Monitoring Wett	1	na	na	na	0	na	
Soil - Pipe Trench	21	na	na	na	ì	na	
Soil - Risk Assessment*	1	0	0	0	0	0	
Soil - Risk Assessment	60	0	0	0	na	1	




## **Building 8 Results**

- Sediments
  - No detections above Screening Level for TPH
- · Soil (Monitoring Well)
  - Additional boring adjacent to monitoring well 08MW-02 did not detect TPH contamination above Screening Level
- · Soil (Pipe Trench)
  - One detection of TPH above SL (200 mg/kg) at 08SB-07, concentration was 1065 mg/kg

# **Building 8 Results**

- \* Soil (Risk Assessment)
  - Discretionary sample collected at RA-08SB-15 did not detect TPH above the Screening Level
  - 1,1-Dichloroethene detected at concentration of 0.17 mg/kg (SL = 0.054 mg/kg) at boring location RA-08SB-05 at a depth of 0 to 0.5 feet

### Building 10



## Building 10 Summary Table

			with Detections ening Level
Sample Type	# of Samples Collected	втех	# <u></u>
Soil - UST Closure	17	0	0


# Building 10 Results

- All soil boring samples collected at Building 10 were below Screening Level for BTEX and TPH
- Discretionary samples at deeper borings SRSB-18 and SRSB-19 in this area had detections of TPH above the SL (200 mg/kg) of 550 and 600 mg/kg
- SRSB-16 located northeast of Building 10 had a detection of TPH at a concentration of 530 mg/kg at a depth of 6 to 7 feet

### Additional Risk Assessment Areas

- Northeast Parking Area
- · Railroads
- Roadways







## Additional Risk Assessment Areas Summary Table

:		# of Samples with Detection above Screening Lev					
Investigation Area -	# of Samples Collected	Explosives	Metals	PAHs	PCBs	VOCs	
Northeast Parking Area - Soit Boring	24	7.1	0	0	0	0	
Railroads - Soll Boring	~ 33	na.	ø	n	0	1	
Roadways - Solt Boring-	84	n a	3	0	0	1	
Roadways - Soil Boring (Former Building 9 Area)	12	_ 0	0	0	0	0	

# Northeast Parking Area Results

- Metals
  - No Detections above Screening Levels
- · PAHs
  - No Detections above Screening Levels
- PCR
  - No Detections above Screening Levels
- VOC
  - No Detections above Screening Levels

# Railroads Results

- Metals
  - No Detections above Screening Levels
- PAHs
  - No Detections above Screening Levels
- PCR
  - No Detections above Screening Levels
- VOCs
  - 1,1-Dichloroethene detected at RA-RRSB-10 (0-0.5')
  - Concentration of 0.075J mg/kg (SL = 0.054 mg/kg)

# Roadways Results

- · Explosives
  - Analyzed only in samples RA-RDSB-13, -13E, -14, and -14E due to proximity to former Building 9
  - No detections above Screening Levels
- Metals
  - Antimony (SL = 31 mg/kg)
    - RA-RDSB-16E (0 to 0.5 feet) at a concentration of 34 mg/kg
  - Beryllium (SL = 1.6 mg/kg)
    - RA-RDSB-06 (4 to 5 feet) at a concentration of 2 mg/kg
    - . RA-RDSB-06E (0 to 0.5 feet) at a concentration of 6.7 mg/kg


# Roadways Results (cont.)

- PAHs
  - No Detections above Screening Levels
- PCBs
  - No Detections above Screening Levels
- VOCs
  - 1,1-Dichloroethene detected at RA-RDSB-01E (9-10')
  - Concentration of 0.13 mg/kg (SL = 0.054 mg/kg)

# Sewer System Survey







### Sewer System

- · Wastewater Results
- · Sediment Results
- · Soil Boring Results

### Sewer System Summary Table

		# of Samples with Detections above Screening Level						
Sample Type	# of Samples Collected	Metals	PCBs	SVOCs	ТРН	VOCs		
Wastewater	10	10	(10)	7*	0	7		
Sediment	5	5	5	2*	5	3		
Soil	92	8	0	0	3	0		

Two wastewater and two sediment samples were not analyzed for SVOCs

### Sewer Wastewater Results

- · Metals
  - Arsenic
    - 10 Detections above Screening Level (SL =  $0.045 \,\mu\text{g/L}$ )
    - Min: 0.9J μg/L; Mean: 1.7 μg/L; Max: 3.2 μg/L (02WW-02)
  - Cadmium
  - Only detection above SL (5 μg/L) was 19 μg/L at 02WW-02
  - Lead
    - 8 Detections above Screening Level (SL = 15 μg/L)
    - Min: 15 μg/L; Mean: 106 μg/L; Max: 412 μg/L (02WW-01)

## Sewer Wastewater Results (Cont.)


- PCBs
  - PCB-1248
    - 10 Detections above Screening Level (SL = 0.034 μg/L)
    - Min: 0.13 μg/L; Mean: 1.65 μg/L; Max: 6.8 μg/L (SRWW-04)
- SVOCs
  - Benzidine
    - Only detection above Screening Level was 2.3 μg/L at SRWW-10 (0.00012 μg/L)
  - · Benzo(a)anthracene
    - 7 Detections above Screening Level (SL = 0.0044 μg/L)
    - Min; 0.079 µg/L; Mean: 2.18 µg/L; Max: 9.7 µg/L (SRWW-04)

## Sewer Wastewater Results (Cont.)

- SVOCs (cont.)
  - Benzo(a)pyrene
    - 6 Detections above Screening Level (SL = 0.0092 µg/L)
    - Min: 0.13 μg/L; Mean: 2.62 μg/L; Max: 9.2 μg/L (SRWW-04)
  - Benzo(b)fluoranthene
    - 7 Detections above Screening Level (SL = 0.0044 µg/L)
  - Min: 0.11 μg/L; Mean: 2.95 μg/L; Max: 12 μg/L (SRWW-(H)
  - Benzo(k)fluoranthene
    - 7 Detections above Screening Level (SL = 0.0044 µg/L)
    - Min: 0.092 μg/L; Mean: 1.64 μg/L; Max: 5.8 μg/L (SRWW-04)

### Sewer Wastewater Results (Cont.)

- SVOCs (cont.)
  - Chrysene
    - 7 Detections above Screening Level (SL =  $0.0044 \mu g/L$ )
    - Min: 0.079 μg/L; Mean: 2.96 μg/L; Max: 13 μg/L (SRWW-04)
  - --Dibenz(a,h)anthracene
    - 4 Detections above Screening Level (SL = 0.0044 μg/L)
  - Min: 0.21 µg/L; Mean: 0.73 µg/L; Max: 1.8 µg/L (SRWW-04)
- Indeno(1,2,3-cd)pyrene
  - 6 Detections above Screening Level (SL = 0.0044 µg/L)
  - Min: 0.08 μg/L; Mean: 2.40 μg/L; Max; 8.8 μg/L (SRWW-04)



## Sewer Wastewater Results (Cont.)

- VOCs
  - 1,1,1-Trichloroethane
    - Only detection above Screening Level was 340 μg/L at 02WW-02 (SL = 200 μg/L)
  - 1.1-Dichloroethene
    - 3 Detections above Screening Level (SL = 0.046 µg/L)
    - Min: 0.6J μg/L; Mean: 1.3 μg/L; Max: 2.1 μg/L (SRWW-03)
  - 1,2-Dichloroethane
    - 2 Detections above Screening Level (SL =  $0.12 \mu g/L$ )
    - Min: 0.4J μg/L; Mean: 0.8 μg/L; Max: 1.2 μg/L (02WW-02)

### Sewer Wastewater Results (Cont.)

- VOCs (cont.)
  - 1,4-Dichlorobenzene
    - Only detection above Screening Level was 1.2  $\mu$ g/L at SRWW-04 (SL = 0.5  $\mu$ g/L)
  - Carbon Tetrachloride
    - Only detection above Screening Level was 2.1  $\mu g/L$  at SRWW-06 (SL = 0.17  $\mu g/L$ )
  - Chloroethane
    - 3 Detections above Screening Level (SL = 4.6 µg/L)
    - Min: 38 μg/L; Mean: 77 μg/L; Max: 150 μg/L (SRWW-02)

### Sewer Wastewater Results (Cont.)

- VOCs (cont.)
  - Chloroform
    - Only detection above Screening Level was 0.3J µg/L at SRWW-06 (SL = 0.16 µg/L)
  - Methylene Chloride .
    - Only detection above Screening Level was 49 µg/L at 02WW-02 (SL = 4.3 µg/L)
  - Trichloroethene (TCE)
    - Only detection above Screening Level was 10 µg/L at SRWW-11 (SL = 1.6 µg/L)

### Sewer Wastewater Results (Cont.)

- VOCs (cont.)
  - Vinyl Chloride
    - Only detection above Screening Level was 0.5J μg/L at 02WW-02 (SL = 0.041 μg/L)

### Sewer Sediment Results

- Metals
  - Antimony
    - 4 Detections above Screening Level (Soil SL = 31 mg/kg)
  - Min: 39 mg/kg; Mean: 43.8 mg/kg; Max: 55 mg/kg (SRSD-03)
  - Arsenic '
    - 4 Detections above Screening Level (Soil SL = 21.4 mg/kg)
    - Min: 3.2 mg/kg: Mean: 21.3 mg/kg; Max: 31 mg/kg (02SD-01)
  - Chromium . .
    - 3 Detections above Screening Level (Soil SL = 210 mg/kg)
    - Min: 215 mg/kg: Mean: 264 mg/kg: Max: 360 mg/kg (SRSD-02)

### Sewer Sediment Results (cont.)

- · Metals (cont.)
  - Copper
    - Only detection above Screening Level was 1290 mg/kg at SRSD-03 (Soil SL = 1100 mg/kg)
  - Lead
    - Only detection above Screening Level was 3660 mg/kg at SRSD-04 (Soil SL = 1038 mg/kg)
  - Mercury
    - Only detection above Screening Level was 5.24 mg/kg at SRSD-02 (Soit SL = 0.6 mg/kg)

### Sewer Sediment Results (cont.)

- PCBs
  - PCB-1248
    - 5 Detections above Screening Level (Soil SL = 0.22 mg/kg)
    - Min: 3.2 mg/kg; Mean: 18.8 mg/kg; Max: 48 mg/kg (SRSD-02)
  - PCB-1260
    - 3 Detections above Screening Level (Soil SL = 0.22 mg/kg)
    - Min: 0.34J mg/kg; Mean: 1.18 mg/kg; Max: 1.8 mg/kg (02SD-01)
  - Total PCBs
    - Min: 3.54 mg/kg; Mean: 19.6 mg/kg; Max: 49.4 mg/kg (SRSD-02)

### Sewer Sediment Results (cont.)

- SVOCs
  - Di-n-octylphthalate
  - Only detection above Screening Level was 2J mg/kg at SRSD-02  $\cdots$  (Soil SL = 0.3 mg/kg)
  - Acenaphthylene
    - Only detection above Screening Level was 0.59J mg/kg at SRSD-04 (Soil SL = 0.31 mg/kg)
  - Benzo(a)anthracene
    - Only detection above Screening Level was 80 mg/kg at SRSD-04 (Soil SL = 7.24 mg/kg)

## Sewer Sediment Results (cont.)

- SVOCs (cont.)
  - Benzo(a)pyrene
    - Only detection above Screening Level was 66 mg/kg at SRSD-04 (Soil SL = 4,10 mg/kg)
  - Benzo(b)fluoranthene
    - Only detection above Screening Level was 100 mg/kg at SRSD-04 (Soil SL = 4.90 mg/kg)
  - Benzo(g.h.i)perylene
    - Only detection above Screening Level was 44 mg/kg at SRSD-04 (Soil SL = 2.46 mg/kg)

### Sewer Sediment Results (cont.)

- SVOCs (cont.)
  - Benzo(k)fluoranthene
    - Only detection above Screening Level was 40 mg/kg at SRSD-04 (Soil SL = 6.2 mg/kg)
  - Chrysene
    - Only detection above Screening Level was 88 mg/kg at SRSD-04 (Soil SL = 36 mg/kg)
  - Dibenz(a,h)anthracene
    - Only detection above Screening Level was 11 mg/kg at SRSD-04 (Soil SL = 1.52 mg/kg)

# Sewer Sediment Results (cont.)

- SVOCs (cont.)
  - Indeno(1,2,3-cd)pyrene
    - Only detection above Screening Level was 37 mg/kg at SRSD-04 (Soil SL = 1.99 mg/kg)
  - Phenanthrene
    - Only detection above Screening Level was 190 mg/kg at SRSD-04 (Soil SL = 15.2 mg/kg)
- TPH
  - 5 Detections above Screening Level (Soil SL = 200 mg/kg)
  - Min: 6,340 mg/kg (SRSD-04); Mean: 16,806 mg/kg; Max: 37,060 mg/kg (SRSD-02)

### Sewer Sediment Results (cont.)

- VOCs
  - 1,1,1-Trichloroethane
    - Only detection above Screening Level was 3900 mg/kg at 02SD-02 (Soil SL = 630 mg/kg)
  - 1,1-Dichloroethane
    - Only detection above Screening Level was 640 mg/kg at 02SD-02
       (Soil SL = 590 mg/kg)
  - 1,1-Dichloroethen
    - Only detection above Screening Level was 0.083 mg/kg at SRSD-02 (Soil SL = 0.054 mg/kg)

### Sewer Sediment Results (cont.)

- · VOCs (cont.)
  - 1.2-Dichloroethane
    - · Only detection above Screening Level was 0.98 mg/kg at 02SD-02 (Soil SL = 0.35 mg/kg)
  - Chloroethane
    - · 2 Detections above Screening Level (Soil SL = 3 mg/kg)
  - Min: 3 mg/kg (02SD-01); Max: 36 mg/kg (SRSD-02)
  - - Only detection above Screening Level was 0.39 mg/kg at 02SD-02 (Soil SL = 0.24 mg/kg)

### Sewer Sediment Results (cont.)

- VOCs (cont.)
  - Methylene Chloride
    - Only detection above Screening Level was 22J mg/kg at 02SD-02 .. (Soil SL = 8.9 mg/kg)

# Sewer Soil Boring Results

- · Metals
  - - 8 Detections above Screening Level (SL = 1.6 mg/kg)
    - Min: 1.6 mg/kg; Mean: 2.4 mg/kg: Max: 3.6 mg/kg
- - 3 Detections above Screening Level (SL = 200 mg/kg)
  - All in vicinity of Building 10, but below those samples
  - Min: 530 mg/kg; Mean: 560 mg/kg: Max: 600 mg/kg

#### Groundwater

- No water bearing units identified during installation of four new wells (03MW-01, 08MW-01,-02,-03)
- New 4 wells sampled using disposable hand bailers approximately one week after development
- Existing 9 wells purged dry under low flow pumping, samples collected the following day using disposable hand
- No recorded precipitation for 28 days prior to sampling, rain every day during sampling
- Turbidity ranges in wells
  - New wells: 1.5 to 2.8 NTU
  - Existing wells: 2.3 to 12.0 NTU with outliers at 52.4 (SWMW-03) and >1000 NTU (SWMW-07)

# Monitoring Well Results Summary Table

		# of Samples with Detections above Screening Level									
Sample Type	# of Wells = Sampled	Explosives	Metals	Nigate	Phosphrus	Ę	Pesticides	SVOCs	VOC	Chloride*	Fluoride*
Fire Hydrant	1	па	n a	n.e	na.	n a	па		0.6	ı	1
Building 2	· 1·	0	1	0	0	0	0	1	1	0.0	02
Building 3	1	0	1	0	0	0	0	i	0	1	i
Building 8	3	0	3	0	0	0	0	3	٥	2.	2.
Building 10	1	0	Ī	0	0	o	0	1	0	4	n 4
Site-Wide	7	o	7.	0	0	ø	0	7	0	n.	na

\* Screening Levels for Chloride and Flouride were not established (all detections are reported). \* Only two of the three wells in this area were tested for Chloride and Flooride.

# Monitoring Well Results

- Mctals

  - · Detected in all thirteen monitoring wells on site
    - Screening Level (SL) = 0.045 μg/L
  - Concentrations ranged from 0.3J to 7.8 µg/L
  - - . . Detected only in well SWMW-07
    - Concentration was 44 μg/L (SL = 15 μg/L)

### Monitoring Well Results (cont.)

- SVOCs
  - 1,2-Diphenylhydrazine (1 Detection)
    - Concentration:  $0.35J \mu g/L (SL = 0.084 \mu g/L)$
  - Benzo(a)anthracene (10 Detections)
    - Range:  $0.0044 0.066 \,\mu\text{g/L}$  (SL =  $0.0044 \,\mu\text{g/L}$ )
  - Benzo(a)pyrene (10 Detections)
    - Range:  $0.01 0.092 \,\mu\text{g/L}$  (SL =  $0.0092 \,\mu\text{g/L}$ )
  - Benzo(b)fluoranthrene (12 Detections)
    - Range:  $0.0054 0.099 \,\mu\text{g/L}$  (SL =  $0.0044 \,\mu\text{g/L}$ )

# Monitoring Well Results (cont.)

- SVOCs (cont.)
  - Benzo(k)fluoranthene (11 Detections)
    - Range:  $0.0044 0.19 \,\mu\text{g/L}$  (SL =  $0.0044 \,\mu\text{g/L}$ )
  - Chrysene (11 Detections)
    - Range:  $0.0061 0.13 \,\mu\text{g/L}$  (SL =  $0.0044 \,\mu\text{g/L}$ )
  - Dibenz(a,h)anthracene (5 Detections)
    - Range:  $0.0047 0.077 \,\mu\text{g/L}$  (SL =  $0.0044 \,\mu\text{g/L}$ )
  - Indeno(1,2,3-cd)pyrene (5 Detections)
    - Range:  $0.0066 0.11 \,\mu\text{g/L}$  (SL =  $0.0044 \,\mu\text{g/L}$ )

### Monitoring Well Results (cont.)

- VOCs
  - Four compounds detected above SL at only one monitoring well, 02MW-01
    - 1,1-Dichloroethene, 34  $\mu$ g/L (SL = 0.046  $\mu$ g/L)
    - 1,2-Dichloroethane, 0.4  $\mu$ g/L (SL = 0.12  $\mu$ g/L)
    - Carbon Tetrachloride, 1  $\mu$ g/L (SL = 0.17  $\mu$ g/L)
    - Chloroform, 10 μg/L (SL = 0.16 μg/L)

### Monitoring Well Results (cont.)

- Indicator Parameters
  - Chloride
    - Fire Hydrant concentration was 27 mg/L
    - Well concentrations were 5, 7.2 and 95 mg/L
  - Fluoride
    - · Fire Hydrant concentration was 1 mg/L
    - Well concentrations were 0.28, 0.33 and 0.44 mg/L
  - Residual Chlorine
    - Fire Hydrant concentration was 1 mg/L
    - Well concentrations were 0 to 0.5 mg/L

# Baseline Human Health Risk Assessment (HHRA)

- The goal of a Baseline HHRA is to estimate potential risks to current or future receptor populations at a site, assuming that current contamination is not remediated.
- For SLAAP, the HHRA is being developed to support
  potential property transfer. While the most likely future
  use of the sife is industrial or commercial, additional less
  likely scenarios are also evaluated. Results of the HHRA
  will most likely be used to support a "no action"
  determination, deed restriction, site cleanup, or some
  combination thereof.

### Baseline HHRA (cont.)

- Primary medium of concern for the HHRA is soil.
   Groundwater is not used in the area, and exposure potential is limited. Buildings are evaluated separately using existing standards.
- Scenarios to be evaluated quantitatively in the HHRA:
  - Industrial/Commercial worker (surface soil)
  - Excavation worker (subsurface soil)
  - Hypothetical resident (surface soil)



### Baseline HHRA (cont.)

- Areas of Concern (AOCs)
  - Although most of the site is currently paved and/or covered with buildings, we do not know which, if any buildings are to be removed in the future.
  - Individual building footprints
  - Areas surrounding buildings

### Baseline HHRA (cont.)

- Chemicals of Potential Concern (COPCs)
  - Focuses on those classes of compounds known or suspected to be present, based on past site history and results of initial EBS.
  - Site data are screened against conservative screening criteria (CALM and Region IX PRGs) to identify COPCs for evaluation in the HHRA.

## Baseline HHRA (cont.)

- · Chemicals of Potential Concern (cont.)
  - PCBs and PAHs appear to be the primary COPCs, although other chemicals (pesticides, metals, etc.) are found sporadically in some AOCs.
  - Dioxin is a big unknown. Sampling in Building 2 show the presence throughout the building and in soils (surface and subsurface). Dioxin has not been characterized in other areas.

### Baseline HHRA (cont.)

- · Type of risk analysis to be performed
  - Reasonable Maximum Exposure (RME) and Central Tendency Exposure (CTE). RME provides an estimate of upperbound risks among most highly exposed individuals, CTE estimates risks to the "average" receptor.
  - "Hotspot" analysis (data from known areas of contamination) and representative exposure (data averaged across the building footprint).

### Baseline HHRA (cont.)

- · Status of HHRA
  - Data have been collected, validated and entered into database (except for supplemental samples).
  - COPC screening is the next step.